

FIG.1




FIG. 2




FIG.3

	T1	T2	T3	T4	T5	T6
Q21u	ON	ON	OFF	OFF	OFF	OFF
Q31u	OFF	OFF	OFF	ON	ON	OFF
Q21v	OFF	OFF	ON	ON	OFF	OFF
Q31v	ON	OFF	OFF	OFF	OFF	ON
Q21w	OFF	OFF	OFF	OFF	ON	ON
Q31w	OFF	ON	ON	OFF	OFF	OFF

FIG.4




FIG.5




FIG.6




FIG.7

